



Plate 6.1 - Process drain from 25/105B (Factory I NC Section) showing NC accumulation



Plate 6.2 - Acid tank farm (22/102H). Concrete supports show signs of acid erosion.

FIGURE TITLE :

Walkover Photographs (1)

PROJECT :

Bishopton

REPORT NUMBER :

A138-00-R1-1

BAE SYSTEMS



Plate 6.3 - Acid leakage from Spent Acid Storage Pond 34/274, Picrite Section.



Plate 6.4 - Empty phosphorous drums to rear of 50/201, White Phosphorous Section

FIGURE TITLE :

Walkover Photographs (2)

PROJECT :

Bishopton

REPORT NUMBER :

A138-00-R1-1

BAE SYSTEMS



Plate 6.5 - Underground diesel tanks, 28/145.



Plate 6.6 - Main ash dump, Georgetown.

FIGURE TITLE :

Walkover Photographs (3)

PROJECT :

Bishopton

REPORT NUMBER :

A138-00-R1-1

BAE SYSTEMS



Plate 6.7 - Picrite lagoon No. 3A/3B



Plate 6.8 - Picrite lagoon No. 5

FIGURE TITLE :

Walkover Photographs (4)

PROJECT :

Bishopton

REPORT NUMBER :

A138-00-R1-1

BAE SYSTEMS



Plate 6.9 - Nethermill Station Tip No. 1



Plate 6.10 - Nethermill Station Tip No. 2

FIGURE TITLE :

Walkover Photographs (5)

PROJECT :

Bishopton

REPORT NUMBER :

A138-00-R1-1

BAE SYSTEMS