



- Probable Intrusive Remediation
- Probable Cover Remediation
- Other Excavation
- Possible Remediation
- Factory fence
- Property boundary
- Surface Water Course

Figure Title:  
**Figure 5 - Pictorial Representation of Remediation and Earthworks Activities**

Project:  
**Bishopton Stage I Investigation**

Project No: A385-00	Report No. A385-00-R6-1	Scale: NTS
------------------------	----------------------------	---------------



BAE Systems Environmental  
Station Road, Bishopton, Renfrewshire, PA7 5NJ  
Tel. 01505 832025 Fax. 01505 832052