



Obs. No.	Observation
1	1 No. 7 hole granule
2	mixed diameter 7 hole granules and blue centre grain
3	1 No. 7 hole granule
4	a few grains of blue centre
5	few to many grains of 7 hole mixed diameter
6	1 No. 7 hole granule
7	many grains of blue centre and 7 hole
8	few to many brown grains
9	few grains of 7 hole 4 to 5 mm diameter
10	few grains of 7 hole 4 to 5 mm diameter
11	2 No. grains 7 hole
12	1 No. granule 7 hole 5 mm diameter
13	few grains of mixed diameter 7 hole
15	few grains 7 hole
16	30 m either side of this point few to many grains of 7 hole
17	10 m either side of this point few to many grains of 7 hole
18	10 m either side of this point few to many grains of 7 hole
19	few to many grains of 7 hole and blue centre
20	few grains of 7 hole and blue centre
21	3 No. grains 7 hole
22	few to many grains 7 hole
23	few grains of 7 hole and blue centre
24	few grains of 7 hole
25	1 No. granule 7 hole 10 mm diameter
26	1 No. granule with grey centre
27	few grains of 7 hole
28	few grains of 7 hole 3 to 4 mm diameter
29	few grains of 7 hole
31	1 No. granule 7 hole 10 mm diameter
32	few grains 7 hole
33	1 No. granule blue centre
34	1 No. brown granule
35	1 No. 7 hole granule

Figure Title:
Figure 15 - Inspection of Narrow Gauge Track

Project:
Bishopton Stage I Investigation

Project No. A385-00 Report No. A385-00-R4-1 Scale: 1:7,500

BAE SYSTEMS

BAE Systems Environmental
Station Road, Bishopton, Renfrewshire, PA7 5NJ
Tel. 01505 832025 Fax. 01505 832052

- Factory fence
- Site boundary
- Inspected
- Not inspected
- Observation No.

