

## REFERENCES

Reference has been made to the following sources of information:

### **BAE Systems Environmental Reports**

BAE Systems Environmental, 2005, Report No: A385-00-R1-1, Stage 1 Site Investigation Outline Strategy

BAE Systems Environmental, 2005, Report No: A385-00-R3-1, Safety, Health and Environmental (SHE) Plan

BAE Systems Environmental, 2006, Report No: A385-00-R4-1, Stage 1 Site Investigation Factual Report

BAE Systems Environmental, 2006, Report No: A385-00-R5-1, Generic Quantitative Risk Assessment

BAE Systems Environmental, 2005, Report No: A138-00-R1-1, Preliminary Risk Assessment for Land Contamination, Desk Study, Bishopton

BAE Systems Environmental, 2004, Report No: A182-00, Buildings Desk Study Files

BAE Systems Environmental, 2003, Report No: A182-0K-R3-1, Preliminary Ground Investigation, Picrite Lagoons

BAE Systems Environmental Services, 2003, Report No: A263-00-R3-1 Preliminary Geotechnical Investigation

BAE Systems Environmental Services, 2003, Report No: A263-01-R3-1 Preliminary Geotechnical Investigation – Soil Chemical Analysis

BAE Systems Environmental, 2003, Report No: P501-0D-R3-1, Preliminary Geotechnical Investigation

BAE Systems Environmental Services, 2002, Report No: A182-0M-R3-1, Ground Investigation at Boghall Dump

BAE Systems Environmental Services, 2002, Report No: P501-0C-R1-1, Perimeter Boreholes

BAE Systems Environmental Services, 2002, Report No: P501-0C-R2-1, Groundwater, Surface Water and Gas Monitoring 2002/3

RO Environmental Services Group, 1996, Report No: 2214/96/1, Preliminary Site Investigation and Remediation Strategy in Support of the Georgetown Outline Regeneration Feasibility Study

RO Environmental Services Group, 1995, Report No: 2099/95/1, Preliminary Ground Investigation for Contamination at the Burning Grounds

RO Environmental Services Group, 1995, Report No: 2079/95/1, Analysis of Groundwater for Contamination

## **Geology and Hydrogeology**

BGS (Scotland), 1958, Geological Map of Glasgow 1:50000, Sheet 30W Solid

BGS, 2004, Commissioned Report CR/04/047N, 'A GIS of aquifer productivity in Scotland: explanatory notes'

## **Legislation and Statutory Guidance**

Construction (Design and Management) Regulations 1994

Contaminated Land (Scotland) Regulations 2005 (SSI 2005/658)

Part IIA Environmental Protection Act 1990

Nature Conservation (Scotland) Act, 1981

Scottish Executive Circular 1/2000 'Environmental Protection Act 1990:Part IIA Contaminated Land'

Scottish Executive, 2000, Planning Advice Note PAN 33, 'Development of Contaminated Land'

Scottish Executive, 2005, Horticulture Code of Practice

The Wildlife & Countryside Act 1981

## **Reports**

Aspinwall & Co., 1989, Report No: RO2402C, Investigation into the Location of Picrite Lagoons

## **Technical Guidance**

CIRIA, 1995, 'Remedial Treatment for Contaminated Land'

DEFRA and EA, 2004, CLR 11 - 'Model Procedures for the Management of Land Contamination'

Environment Agency, 2001, 'Remedial Treatment Action Data Sheets'

SEPA, 2005, PPG (Pollution Prevention Guidelines) 1, 'General Guide to the Prevention of Water Pollution'

SEPA, 2005, PPG (Pollution Prevention Guidelines) 5, 'Works In, Near or Liable to Affect Watercourses'

SEPA, 2005, PPG (Pollution Prevention Guidelines) 6, 'Working at Construction and Demolition Sites'

SEPA, 2005, PPG (Pollution Prevention Guidelines) 7, 'Refuelling Facilities'

SEPA, 2000, 'Ponds, Pools and Lochans: Guidance on Good Practice in the Management and Creation of Small Waterbodies in Scotland'